

# Power System Operating Incident Report – Trip of Ringwood No.2 220 kV Busbar on 29 January 2014

PREPARED BY: AEMO Systems Capability

DATE: 4 April 2014

STATUS: FINAL

Australian Energy Market Operator Ltd ABN 94 072 010 327

www.aemo.com.au info@aemo.com.au



# **Version Release History**

VERSION	DATE	BY	CHANGES	CHECKED BY	AUTHORISED BY
1	4 April 2014	S Darnell	FINAL	S Darnell	P Biddle

## **Incident Classifications**

Time and date and of incident	1345 hrs Wednesday 29 January 2014
Region of incident	Victoria
Affected regions	Victoria
Event type	OTH – Other
Primary cause	OE & CON – Operating Error and Non-Conformance
Impact	Nil
Associated reports	Nil

# **Abbreviations**

Abbreviation	Term
AEMO	Australian Energy Market Operator
EMMS	Electricity Market Management System
EMS	Energy Management System
kV	Kilovolt
NER	National Electricity Rules

## Disclaimer

#### **Purpose**

This report has been prepared by the Australian Energy Market Operator Limited (**AEMO**) for the sole purpose of meeting obligations in accordance with clause 4.8.15 (c) of the National Electricity Rules (NER).

#### No reliance or warranty

This report contains data provided by third parties and might contain conclusions or forecasts and the like that rely on that data. This data might not be free from errors or omissions. While AEMO has used due care and skill, AEMO does not warrant or represent that the data, conclusions, forecasts or other information in this report are accurate, reliable, complete or current or that they are suitable for particular purposes. You should verify and check the accuracy, completeness, reliability and suitability of this report for any use to which you intend to put it, and seek independent expert advice before using it, or any information contained in it.

#### Limitation of liability

To the extent permitted by law, AEMO and its advisers, consultants and other contributors to this report (or their respective associated companies, businesses, partners, directors, officers or employees) shall not be liable for any errors, omissions, defects or misrepresentations in the information contained in this report, or for any loss or damage suffered by persons who use or rely on such information (including by reason of negligence, negligent misstatement or otherwise). If any law prohibits the exclusion of such liability, AEMO's liability is limited, at AEMO's option, to the resupply of the information, provided that this limitation is permitted by law and is fair and reasonable.

© 2014 Australian Energy Market Operator Ltd. All rights reserved



## 1 Introduction


This report reviews a power system operating incident<sup>1</sup> that occurred on Wednesday 29 January 2014 at Ringwood Terminal Station in Victoria. The purpose of this incident review is to assess power system security over the course of the incident<sup>2</sup>. This report is based upon information provided by SP AusNet<sup>3</sup>. National Electricity Market time (Australian Eastern Standard Time) is used in this report.

#### 2 The Incident

On Wednesday 29 January 2014 at 1345 hrs the Ringwood No.2 220 kV busbar tripped. There was no loss of load or generation and the power system remained secure.

The reason for investigating this incident that a 220 kV busbar tripped. The probability of a busbar fault is very low and is thereby an unexpected event known in power system security terms as a non-credible contingency<sup>4</sup>.

The status of the power system before and after the incident is shown below. The After diagram shows all circuit breakers connected to the No.2 busbar open.



# 3 Investigation

SP AusNet investigated this incident and found that the trip was caused by staff working in the Ringwood Terminal Station. A damaged in-service control cable was inadvertently disturbed, which then operated the busbar Y protection relay.

SP AusNet isolated the Y protection relay and returned the busbar to service 48 minutes after the incident. SP AusNet then repaired the damaged cable and returned the Y protection relay to service at 1720 hrs on the same day.

4 April 2014 Page 2 of 3

<sup>&</sup>lt;sup>1</sup> AEMO is required to review this incident as it is classified as a non-credible contingency that satisfies the requirements of a reviewable operating incident under the National Electricity Rules (NER) - NER Clause 4.8.15(a)(1)(i) and AEMC Reliability Panel Guidelines for Identifying Reviewable Operating Incidents.

<sup>&</sup>lt;sup>2</sup> The NER requires AEMO to assess the adequacy of the provision and response of facilities and services and the appropriateness of actions taken to restore or maintain power system security - NER Clause 4.8.15 (b)

<sup>&</sup>lt;sup>3</sup> SP AusNet is the Transmission Network Service Provider in Victoria. Information provided by SP AusNet has been provided on a without prejudice basis and nothing in this report is intended to constitute, or may be taken by any person as constituting, an admission of fault, liability, wrongdoing, negligence, bad faith or the like on behalf of SP AusNet (or its respective associated companies, businesses, partners, directors, officers or employees).

<sup>&</sup>lt;sup>4</sup> NER v60 4.2.3 - Credible and non-credible contingency events; *AEMO Power System Security Guidelines,* Section 10 - Definition of a non-credible contingency events



# 4 Power System Security

This section assesses how AEMO managed power system security over the course of the incident<sup>5</sup>.

AEMO did not invoke any constraint sets for this incident because the power system was in a secure state<sup>6</sup>. SP AusNet promptly identified the cause of the incident and notified AEMO. SP AusNet then returned the busbar to service with Y protection disabled.

AEMO issued Market notice 44821 at 1419hrs<sup>7</sup> to notify the market:

- Of the non-credible contingency.
- That AEMO had not reclassified the incident as a credible contingency.

AEMO did not reclassify the incident because the cause of the incident had been identified, and AEMO considered the incident unlikely to reoccur.<sup>8</sup>

Power system security was maintained over the course of the incident.

## 5 Conclusions

- 1. The Ringwood No. 2 220 kV busbar tripped due to a damaged in-service control cable that caused an inadvertent protection relay operation.
- 2. Power system security was maintained over the course of the incident.

#### 6 Recommendations

There are no recommendation arising from this incident.

4 April 2014 Page 3 of 3

<sup>&</sup>lt;sup>5</sup> AEMO is responsible for power system security in the NEM and is required to operate the power system in a secure operating state (NER Clause 4.2.4 (a)). AEMO must thereby ensure that the power system is maintained in, or returned to, a secure operating state following a contingency event.

<sup>&</sup>lt;sup>6</sup> AEMO is required to return the power system to a secure state within thirty minutes following a contingency event - NER Clause 4.2.6 (b)

<sup>&</sup>lt;sup>7</sup> This is was within two hours of the event in which AEMO is required to notify the market of a non-credible contingency event AEMO - *Power System Security Guidelines,* Section 10.3

<sup>&</sup>lt;sup>8</sup> For a non credible contingency AEMO is required to assess whether or not to reclassify a non credible contingency event as a credible contingency (NER Clause 4.2.3A (c)) and to report how re-classification criteria were applied NER Clause 4.8.15 (ca). AEMO has to determine if the condition that caused the non-credible contingency event has been resolved.